



Wash & Care Symbols

USA

USA WASH CARE SYMBOLS

As a minimum, laundering instructions should include four symbols - washing, bleaching, drying and ironing (in that order). Drycleaning instructions can also be included. Additional words can be used to clarify any instructions.

Wash

MACHINE WASH CYCLES



WATER TEMPERATURES

Maximum Temperature	200F	160F	140F	120F	105F	65-85F
Symbols	95C ••••	70C ••••	60C ••••	50C ••••	40C ••••	30C •

ADDITIONAL SYMBOLS



Bleach




Dry

DRY CYCLES & OPTIONS



TUMBLE DRY HEAT SETTINGS



USA WASH CARE SYMBOLS

Iron

IRON DRY OR STEAM



200C
(390F)
High



150C
(300F)
Medium



110C
(230F)
Low



Do Not Iron



No Steam
(added to iron symbol)

Dryclean

DRY CLEAN - NORMAL CYCLE



Any Solvent



Any Solvent
Except
Trichloroethylene



Petroleum
Solvent Only



Do Not Dryclean

DRY CLEAN - ADDITIONAL INSTRUCTIONS



Short Cycle



Reduce Moisture



Low Heat



No Steam
Finishing

www.ukpaccessories.com

enquiries@ukpaccessories.com

U.K.P. Accessories
garment branding, labelling & packaging