



Wash & Care Symbols

CHINA

CHINESE WASH CARE SYMBOLS

For the Chinese labelling standards, there are 5 main sections appearing in the following order - washing, bleaching, drying, ironing and professional cleaning.

Washing


 Max. Temperature: 95°C
Normal Process

 Max. Temperature: 60°C
Mild Process

 Wash By Hand
Max. Temperature 40°C

 Max. Temperature: 70°C
Normal Process

 Max. Temperature: 50°C
Mild Process

 Do Not Wash

 Max. Temperature: 60°C
Normal Process

 Max. Temperature: 40°C
Mild Process

 Max. Temperature: 50°C
Normal Process

 Max. Temperature: 30°C
Mild Process

 Max. Temperature: 40°C
Normal Process

 Max. Temperature: 40°C
Very Mild Process

 Max. Temperature: 30°C
Normal Process

 Max. Temperature: 30°C
Very Mild Process

Bleaching



Any bleaching
agent allowed



Only oxygen /
non-chlorine bleach
allowed



Do Not Bleach

Drying

DRY CYCLES & OPTIONS



Normal



Permanent Press



Delicate/Gentle



Line Dry/
Hang to Dry



Do Not
Tumble Dry

CHINESE WASH CARE SYMBOLS





□ Drying cont...

NATURAL DRYING SYMBOLS

			
Line Drying	Drip Line Drying	Flat Drying	Drip Flat Drying
			
Line Drying In The Shade	Drip Line Drying In The Shade	Flat Drying In The Shade	Drip Flat Drying In The Shade






☞ Ironing

IRON DRY OR STEAM





			
Iron at max. temperature of 200°C	Iron at max. temperature of 150°C	Iron at max. temperature of 110°C	Do Not Iron

○ Professional Textile Care

PROFESSIONAL DRY CLEANING

				
Professional dry cleaning in tetrachloroethene and all solvents listed for the symbol F. Normal Process	Professional dry cleaning in tetrachloroethene and all solvents listed for the symbol F. Mild Process	Professional dry cleaning in hydrocarbons (distillation temperature between 150 C and 210 C, flash point between 38 C and 70 C) Normal Process	Professional dry cleaning in hydrocarbons (distillation temperature between 150 C and 210 C, flash point between 38 C and 70 C) Mild Process	Do Not Dry Clean

PROFESSIONAL WET CLEANING

			
Professional wet cleaning. Normal Process	Professional wet cleaning. Mild Process	Professional wet cleaning. Very Mild Process	Do Not Professional Wet Clean

www.ukpaccessories.com

enquiries@ukpaccessories.com

U.K.P. Accessories
garment branding, labelling & packaging